

Index File No. T-3

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____

T 1N R. 37E.

R.D. Walla Walla County Umatilla


Merid. W.M.

N.F. Umatilla State OR

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

None



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

SOUTH OF CREEK ON STEEP WOODED NORTH SLOPE

Signature

Michael P. Ferguson PLS

Title

Division

Headquarters

Date

10/93

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

At a section subdivision as determined by this survey set a 3/4" aluminum cap on a 2 1/2" x 30" aluminum pipe, 26" in the ground.

TIN R37E
S30
C 1/4 +
PLS 2535
1993

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

- 9" Douglas Fir bears N. 23 1/2° E., 17.5' scribed C 1/4 S30BT
- 14" Douglas Fir bears N. 66 1/2° W., 7.6' scribed C 1/4 S30BT
- 16" Douglas Fir bears N. 76° E., 7.1' scribed C 1/4 S30BT
- 17" Douglas Fir bears S. 40 1/2° W., 16.2' scribed C 1/4 S30BT

Work Done By Le June Title PLS Date 9/98 State Registration No. or Agency 2535

Certified Cor. Record Prepared? Yes No Filed At: Date

REMARKS