

USDA-FOREST SERVICE

Index
File No. F-05

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____ Cor.
No. _____

T 1S R. 36E

R.D. WALLA WALLA County UMATILLA

Merid. W.M.

N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

FND 3 1/4" BLM BRASS CAP RISING 4"
ABOVE GROUND.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

13" W. FIR, BLAZED & SCRIBED N 1/6 S7 BT,
BEARS N 79 3/4° W, 32 LKS., 21.1 FT.
14" D. FIR, BLAZED & SCRIBED N 1/6 S8 BT,
BEARS S 89 1/4° E, 48 1/2 LKS., 32.0 FT.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

NORTHWESTERLY 0.4 MI. FROM HORON SIDING.
CORNER IS WEST UP HILL FROM END OF CURVE
250' ON STEEP NORTHEASTERLY SLOPE TO NW 1/6 S8.
FOLLOW POSTED LINE WEST 1/4 MI TO CORNER

Signature

[Handwritten Signature]

Title

LS1848

Division

Headquarters

Date

7-85

7100-52 (3. 68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

NONE

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

SET STEEL FENCE POST 3' EAST
ATTACHED SIGNS TO POST & BT'S.

Work Done By B.A. SUTTON Title SURVEYOR Date 7/85 State Registration No. LS 1848
or Agency

Certified Cor. Record Prepared? Yes No Filed At:

Date

REMARKS

Index File No. F-05 T. 1S R. 36E M. W.M. Tract or Surv. No.

Cor.

13/16
7/8

12

13