

USDA-FOREST SERVICE

Index

File No. G-08

T 1S R. 36E

Merid. W.M.

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

R.D. WALLAWALLA County UMATILLA

N.F. UMATILLA State OREGON

Tract or Survey No. _____ Cor. No. _____

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

3/4" BLM BRASS CAP ON 2 1/2" IP RISING 8"

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

13" PONDEROSA PINE, BLAZED & SCRIBED CE 1/6 S8 BT
BEARS N 62 1/2° E - 31 LKS - 20 1/2 FT.

13" PONDEROSA PINE, BLAZED & SCRIBED CE 1/6 S8 BT
BEARS S 48 1/4° E - 68 LKS - 44.9 FT.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FROM C 1/4 S8 BY RR. TRACKS, FOLLOW
POSTED LINE 1/4 MILE EAST UP THE HILL.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

[Handwritten Signature]

Title LS 1848

Division

Headquarters

Date

7-85

7100-52 (3.68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

NONE

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

SET STEEL FENCE POST 3' EAST OF CORNER
ATTACHED SIGNS TO POST & BT'S.

Painted Red Bands

Work Done By BA SUTTON Title SURVEYOR Date 7-85 State Registration No. or Agency LS 1848

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File No.
G-08

T. 15 R. 36E W.M.

Tract or Surv. No.

Cor.
CE 1/1658