

**PUBLIC LAND CORNER CONDITION REPORT**

**UMATILLA COUNTY, DATE: 02/26/02**

**CORNER DESIGNATION: 2N32A21, The Northeast Corner of Section 2.**

**PREVIOUS RENEWALS/ SURVEYS, ETC..:**

Most recent Umatilla County Surveyors recorded corner record: 88-19-C.

**MONUMENT AND ACCESSORIES FOUND:**

Found a 2 1/2" brass cap flush with ground marked as shown in monument marking detail. As per corner record, everything is as stated except the aluminum nail N 50° W, 1.12' is in East side of cut off power pole not North side.

**MONUMENT MARKING DETAIL:**

T3N R32E  
S35 | S36  
S2 | S1  
T2N R32E  
1988  
PLS 1106

**LOCATION & COMMENTS:**

Located at the North end of a South running fence.

**STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:**

N = 742038.72  
E = 8645120.14

**FIRM/AGENCY:** William R. Wells  
P.O. Box 1696  
Pendleton, Oregon 97801

2N32A21

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Will. R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

*renews 6/30/02*

*From D. Nevens*

05  
26  
05

**RECEIVED BY**

**Umatilla County Surveyor**

Date 5-02

Rec'd By KK

No. 02-108-9