

**PUBLIC LAND CORNER CONDITION REPORT**

**UMATILLA COUNTY, DATE: 10/22/01**

**CORNER DESIGNATION: 2N32, C-5, The East 1/4 Corner of Section 6.**

**PREVIOUS RENEWALS/ SURVEYS, ETC.:**

Most current is Umatilla County Surveyor's Corner Record No. 88-19-C.

**MONUMENT AND ACCESSORIES FOUND:**

Found a 2 1/2" brass cap with top 2" above ground level with a ring of stones around it in good condition, marked as shown in monument marking detail.

As per Corner Record, all accessories exist although the witness post sign and bearing object sign for Northerly accessory has been burned and is barely readable.

Witness post sign 3 feet +/- Southerly from monument is also burned and unreadable.

Corner has only 2 accessories.

**MONUMENT MARKING DETAIL:**

T2N R32E

1/4

S6 | S5

1988

PLS 1106

**LOCATION & COMMENTS:**

Corner is located in old road bed approximately 30' East of a North/South fence.

**STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, IN <sup>5</sup>/<sub>8</sub> FOOT:**

N = 738920.74

E = 8624103.17

**FIRM/AGENCY:**

William R. Wells, PLS  
P.O. Box 1696  
Pendleton, Oregon 97801

*Handwritten:*  
2N32C5  
R. Wells

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Handwritten:* Will. R. Wells

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

*Handwritten:* renews 6-30-02

RECEIVED BY

Umatilla County Surveyor

Date 12-01

Rec'd By KK

No. 01-210-9

05  
26  
05