

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 12/31/01

CORNER DESIGNATION: 2N32, J-17, the Northeast Corner of Section 15.

PREVIOUS RENEWALS/ SURVEYS, ETC..:

Corner was most recently maintained under Umatilla County Surveyor's Corner Record No. 90-50-C and accompanying Record of Survey.

MONUMENT AND ACCESSORIES FOUND:

Found a 2 1/2" brass cap monument on galvanized iron pipe, buried 6" below ground, marked as shown in monument marking detail. As per Corner Record accessories are intact. Corner has four accessories.

MONUMENT MARKING DETAIL:

RLS 346
10 | 11

15 | 14
T2N R32E

LOCATION & COMMENTS:

Corner located in East-West fence line on South side of West Slope Park Subdivision.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 731392.30
E = 8640090.42

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801

12N32J17

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Will. R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 06-30-02

05
26
05

Karen A. Norman

RECEIVED BY
Umatilla County Surveyor
Date 2-02
Rec'd by KK
No. 02-46-g