

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 12/31/01

CORNER DESIGNATION: 2N32, L-21, The East 1/4 Corner of Section 14.

PREVIOUS RENEWALS/ SURVEYS, ETC..:

Corner was reestablished under Umatilla County Surveyor's Corner Record No. 92-92-C and accompanying Record of Survey.

MONUMENT AND ACCESSORIES FOUND:

Found a 2 1/2" brass cap monument on galvanized iron pipe, buried 14" below ground, marked as shown in monument marking detail. As per Corner Record accessories are O.K. except the bearing object signs have been shot up. Corner has four accessories.

MONUMENT MARKING DETAIL:

T2N R32E
1/4
S14 | S13
1992
PLS 1106

LOCATION & COMMENTS:

Corner located on West side of old Dump Road, just North of Bridge.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 728858.41
E = 8645437.90

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801

√2N32L21

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-03

Fawn A. Neumann

05
26
05

RECEIVED BY

Umatilla County Surveyor
Date 2-02
Rec'd By KE
No. 02-46-g