

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 11/15/01

CORNER DESIGNATION: 2N32, R-25, The Southeast Corner of Section 24.

PREVIOUS RENEWALS/ SURVEYS, ETC.:

Most recent is Umatilla County Surveyor's Corner Record 93-54-C.

MONUMENT AND ACCESSORIES FOUND:

Found a 2 1/2" brass cap monument 12" below gravel road surface, marked as shown in monument marking detail. Per Corner Record all certificates are in place except the 5/8" iron rod at S 15° W, 51.8 feet has been bent by farming and bearing object sign is gone. "Witness" sign is gone from steel fence post at 5.0 feet West of Corner. The Corner has four accessories.

MONUMENT MARKING DETAIL:

T2N
R32E S24| R33E
S25|
1993
PLS 1106

LOCATION & COMMENTS:

Located at West edge of Goad Road in a pull off area by mailboxes.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 720994.98

E = 8650903.57

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801

2N32R25

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Will. R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-02

RECEIVED BY

Umatilla County Surveyor

Date 12-01

Rec'd By JK

No. 01-210-9