

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 12/20/01

CORNER DESIGNATION: 2N33E17, Northeast Corner of Section 10.

PREVIOUS RENEWALS/ SURVEYS, ETC.:

Most recent Umatilla County Surveyors recorded survey: 00-160-B. This is a witness corner monument set 2 links South of corner point by L.E. Wilkes in 1917.

MONUMENT AND ACCESSORIES FOUND:

Found 2 1/2" brass cap on a 2" galvanized iron pipe approximately 12" above ground level in center of spring branch, marked as shown in monument marking detail. This is a witness corner monument set 2 links South of true corner point.

MONUMENT MARKING DETAIL:

US GLO5
02 lk
WC
T2N R33E
S3 | S2
S10|S11
1917

LOCATION & COMMENTS:

Located in center of small spring branch.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

True corner point:
N= 737469.28
E=8671605.12
Witness corner monument 2 links South:
N= 737467.96
E= 8671605.15

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801

2N33E17

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1917
WILLIAM R. WELLS
1106

renews 6-30-02

RECEIVED BY

Umatilla County Surveyor

Date 2-02

Rec'd by KK

No. 02-43-9