

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 11/15/01

CORNER DESIGNATION: 2N33, G-1, The West 1/4 Corner of Section 7 only.

PREVIOUS RENEWALS/ SURVEYS, ETC.:

Corner was established in a survey by Wilkes, on the West Boundary of the Diminished Reservation Boundary, in 1917. There is No Current Corner Record for this Corner. See Survey No. 90-50-C.

MONUMENT AND ACCESSORIES FOUND:

Found a 2 1/2" brass cap on iron pipe, 4" above ground level in North/South fence, marked as shown in monument marking detail.

MONUMENT MARKING DETAIL:

Corner stamped: US GLO

┌
| 1/4 S7
1917

LOCATION & COMMENTS:

This corner is in a North/South fenceline.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 734452.91

E = 8650603.20

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801

2N33G1

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1997
WILLIAM R. WELLS
1106

renews 6-30-02

RECEIVED BY

Umatilla County Surveyor

Date 12-01

Rec'd By KF

File No. 01-211-9