

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 12/20/01

CORNER DESIGNATION: 2N33G25, The East Quarter Corner of Section 12.

PREVIOUS RENEWALS/ SURVEYS, ETC..:

Most recent Umatilla County Surveyors recorded survey: 99-164-B.

MONUMENT AND ACCESSORIES FOUND:

Found 1 1/2" aluminum cap on 5/8" rebar set in 3" pipe filled with concrete, buried approximately 1 foot below West edge of gravel road, approximately 8 feet East of fence corner. No visible accessories, marked as shown in monument marking detail.

MONUMENT MARKING DETAIL:

EAST 1/4 COR SEC 12
LS 1861

LOCATION & COMMENTS:

Approximately 1 foot below West edge of gravel road, approximately 8 feet East of fence corner.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 735050.39
E = 8682234.02

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801

2N33G25

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-20-02

RECEIVED BY

Umatilla County Surveyors

Date 2-02

Rec'd By KR

No. 02-43-9