

**PUBLIC LAND CORNER CONDITION REPORT**

**UMATILLA COUNTY, DATE: 10/02/01**

**CORNER DESIGNATION: 2N33J15, The North 1/4 Corner of Section 15.**

**PREVIOUS RENEWALS/ SURVEYS, ETC.:**

Corner recovered on Umatilla County Survey No. 93-053-C.

**MONUMENT AND ACCESSORIES FOUND:**

Found a 2 1/2" brass cap 6" below ground at the corner of a field line that runs South and West. Top of cap is marked slightly but still fairly legible, marked as shown in monument marking detail. This is a Wilkes monument from 1917 GLO survey.

A steel fence post with witness post sign 2.0 feet Northeast of monument. No other visible accessories.

**MONUMENT MARKING DETAIL:**

GLO  
1/4 S10  
S15  
1917

**LOCATION & COMMENTS:**

Corner is located at corner of farmed fields.

**STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:**

N = 732113.29  
E = 8669042.07

**FIRM/AGENCY:** William R. Wells  
P.O. Box 1696  
Pendleton, Oregon 97801

\2N33J15

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

*renews 6/30/02*

RECEIVED BY

Umatilla County Surveyor

Date 5-02

Rec'd By KK

No. 02-111-9