

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 02/20/02

CORNER DESIGNATION: 2N33L9, The East 1/4 Corner of Section 17.

PREVIOUS RENEWALS/ SURVEYS, ETC..:

Most recent Umatilla County Surveyors Corner Record: 97-222-C.

MONUMENT AND ACCESSORIES FOUND:

Found a 2 1/2" brass cap 4" above ground level.
Monument marked as shown in monument marking detail.
As per corner record all accessories are intact.

MONUMENT MARKING DETAIL:

T2N R33E
1/4
S17 | S16
1997
PLS 1106

LOCATION & COMMENTS:

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 729336.45
E = 8661115.38

FIRM/AGENCY: William R. Wells
P.O. Box 1696
Pendleton, Oregon 97801

2N33L9

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6/30/02

RECEIVED BY
Umatilla County Surveyors
Date 5-02
Rec'd By KK
No. 02-113-9