

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 01/18/02

CORNER DESIGNATION: 2N33V21, The Northeast Corner of Section 35.

PREVIOUS RENEWALS/ SURVEYS, ETC..:

Most recent Umatilla County Surveyors recorded survey: 82-57-C.

MONUMENT AND ACCESSORIES FOUND:

Found 2 1/2" brass cap on iron pipe monument in 3 foot diameter mound of earth with top 4" above ground level, marked as shown in monument marking detail. There is a steel fence post with witness post sign located 1.5 feet from monument.

MONUMENT MARKING DETAIL:

INDIAN ALLOTMENT

S26 | S25

S35 | S36

T2N R33E

LOCATION & COMMENTS:

Corner located near fence intersection with fences extending East, West and North.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 716306.38

E = 8677364.59

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801

2N33V21

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-02

RECEIVED BY

Umatilla County Surveyors

Date 2-02

Rec'd by KE

No. 02-43-9