

**PUBLIC LAND CORNER CONDITION REPORT**

**UMATILLA COUNTY, DATE: 11/16/01**

**CORNER DESIGNATION: 2N32, X-25, The East 1/4 Corner of Section 36.**

**PREVIOUS RENEWALS/ SURVEYS, ETC.:**

Most current is Umatilla County Surveyor's Corner Record: 94-109-C.

**MONUMENT AND ACCESSORIES FOUND:**

Found a 2 1/2" brass cap monument with cap buried 14" below Goad Road surface, monument marked as shown in monument marking diagram.

All accessories are intact per the record Corner Record. The corner has four accessories.

**MONUMENT MARKING DETAIL:**

T2N  
R32E | R33E  
1/4  
S36 | S31  
1994  
PLS 1106

**LOCATION & COMMENTS:**

Corner located 3 feet West of centerline of Goad Road.

**STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:**

N = 713073.57

E = 8651089.22

**FIRM/AGENCY:** William R. Wells, PLS  
P.O. Box 1696  
Pendleton, Oregon 97801

2N32X25

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

*renews 6-30-02*

RECEIVED BY

Umatilla County Surveyor

Date 12-01

Rec'd By KK

No. 01-210-9