

**PUBLIC LAND CORNER CONDITION REPORT**

**UMATILLA COUNTY, DATE:** 01/02/02

**CORNER DESIGNATION:** 2N33X21, The East Quarter Corner of Section 35.

**PREVIOUS RENEWALS/ SURVEYS, ETC.:**

Most recent Umatilla County Surveyors recorded survey record: 96-113-C.

**MONUMENT AND ACCESSORIES FOUND:**

Found 2 1/2" brass cap on 2" galvanized iron pipe, 2 1/2 feet above ground level, leaning. This is a C.E. Redfield monument from Indian Allotment Surveys.

**MONUMENT MARKING DETAIL:**

T2N R33E  
1/4  
35 | 36

**LOCATION & COMMENTS:**

Straightened monument and firmed up with rocks.

**STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:**

N = 713685.09  
E = 8677423.42

**FIRM/AGENCY:** William R. Wells  
P.O. Box 1696  
Pendleton, Oregon 97801

2N33X21

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

*renews 6/30/02*

RECEIVED BY

Umatilla County Surveyors

Date 5-02

Rec'd By KF

No. 02-126-9