

USDA-FOREST SERVICE

Index File No. J-19

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____

T 2N R. 37E


R.D. WALLA WALLA County UMATILLA

Merid. Will

N.F. UMATILLA State OREGON

CORNER DIAGRAM

T2N R37E



DESCRIBE CORNER MONUMENT FOUND

MOUND OF STONES AT CORNER - NONE WITH VISIBLE MARKS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

ORIG. 40" PINE IS DOWN - SCRIBES "1/4 5" ARE VISIBLE ON OPEN BLAZE. ROOT HOLE BEARS 574°E, 118 LINKS (77.88 FT.) I PUT A BT SIGN ON ROOT ABOVE BLAZE, ORIG, 24" POND, PINE LINE TREE IS LIVE & BEARS EAST, 652.7 FT. & HAS DOUBLE HEALED

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

NOTCHES ON EAST & WEST SIDES. LINE TREE IS VISIBLE FROM CORNER. I PUT BT SIGNS ON LINE TREE.

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

Jennies L. Gaylord PLS 1636

10-30-89

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor. 13