

Index
File No. V-23

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____
Cor. No. _____

T 2 S. R. 34 E. R.D. _____ County UMATILLA

Merid. WILLAMETTE N.F. UMATILLA State OREGON

CORNER DIAGRAM



$\frac{1}{4}$ S. 25
S. 36

DESCRIBE CORNER MONUMENT FOUND

2 1/2" DIAM. BRASS CAP SET ON A 1" O.D. IRON PIPE IN A STONE MOUND. REMAINS OF OLD FENCE LINE RUNS E-W. CAP MKD. PER SKETCH. 1917

$\frac{1}{4}$ S. 25
S. 36

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

20" D.B.H. (12") PONDEROSA PINE, N. 88° 45' E., 459 LKS., w/HEALED DOUBLE FACE.

29" D.B.H. (16") PONDEROSA PINE, S. 6° 45' W., 264', w/SINGLE HEALED FACE.

EACH B.T. HAS B.T. TAG, ATTN. SIGN & BANDS PAINTED RED.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

TAKE ROAD 21 TO WEST LINE OF S. 31, T. 25, R. 35 E., TAKE ROAD NORTH FOR 1.22 MILES TO SOUTH LINE OF S. 25, 1/4 CORNER $\frac{S. 25}{S. 36}$ IS IN MEADOW 300'± WEST AND CAN BE EASILY SEEN FROM ROAD.

Signature _____

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

Clinton J. [Signature]

LAND SURVEYOR

7-9-85

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

RAISED STONE MOUND, SET STEEL POSTS 3'± E. & W. w/ SIGNS ATTACHED. RESET MONUMENT WHICH WAS LOOSE IN MOUND.

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By. _____ Title _____ Date _____ State Registration No. or Agency _____
Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File No. V-23 T. 2 S. R. 34 E. M. WILLAMETTE Tract or Surv. No.

Cor. 5.25
1/4 5.36


Index
File No. V-23
T 2S R. 34E
Merid. WILL

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____
R.D. UKIAH County UMATILLA / UNION
N.F. UMATILLA State ORE

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

BRASS CAPPED IRON PIPE LOOSELY SET IN A MOUND OF STONES

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

ORIG. 16" PINE IS LIVE WITH A SINGLE HEALED BLAZE & BEARS $56^{\circ}45'W$, 264.0 FT

ORIG. 12" PINE IS LIVE WITH DOUBLE HEALED BLAZES & BEARS $N88^{\circ}45'W$, 302.9 FT.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

JUST NORTH OF JEEP ROAD.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature

Title

Division

Headquarters

Date

7100-52 (3. 68)

Dennis L. Haylovd

PLS 1636

5-24-84

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor.