

GOVERNMENT CORNER RESTORATION FORM

Township 3N Range 29E Sec. 5/4  
8/9 County UMATILLA  
State OREGON Date July 19, 1991 No. E-9

Corner Designation

SECTION CORNER  $\frac{5}{8} \frac{4}{9}$

- Condition Report Only
  - Not Found
  - Renewed
  - Unrecorded
  - Surveyed In
  - Referenced Out
- MONUMENT DETAIL

Previous Renewals \_\_\_\_\_

Monument(s) Found: (Condition and Source)

FOUND 2 1/2" BRASS CAP ON 1 1/2" GALV  
IRON PIPE, 4" ABOVE GROUND IN GOOD  
CONDITION WITH WITNESS SIGN AND POST  
ALIP S.H.R.W. SIGN POST, MARKED  
AS SHOWN



Accessories Found: NONE

RECEIVED  
LAND SURVEYOR  
DEPARTMENT

RECEIVED BY  
Umatilla County Surveyor  
Date 9-91  
Rec'd By RR  
No. 91 61-B

UMATILLA COUNTY SURVEYOR

Received \_\_\_\_\_

Recorded \_\_\_\_\_

Survey Inst. No. \_\_\_\_\_

File No. \_\_\_\_\_