

USDA-FOREST SERVICE

Index Y-9  
 File No. \_\_\_\_\_

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or Survey No. \_\_\_\_\_  
 Cor. No. \_\_\_\_\_

T 3N R. 36E R.D. WALLA WALLA County UMATILLA

Merid. WILLAMETTE N.F. UMATILLA State OREGON

CORNER DIAGRAM

INDIAN ALLOTMENT



DESCRIBE CORNER MONUMENT FOUND

BRASS CAPPED IRON PIPE, CAP IS MARKED AS SHOWN IN CORNER DIAGRAM.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
 Filed At. \_\_\_\_\_  
 Object Ident. \_\_\_\_\_  
 Ident. By \_\_\_\_\_  
 Signature \_\_\_\_\_

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
 X \_\_\_\_\_  
 Y \_\_\_\_\_  
 Estab. By \_\_\_\_\_  
 Agency \_\_\_\_\_

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

THIS CORNER MONUMENT IS ABOUT 15 FEET NORTH OF THE CLOSING CORNER MONUMENT SET AT THE INTERSECTION OF THE RESERVATION BOUNDARY WITH THE SECTION LINE BETWEEN SECTIONS 32 & 33. ABOUT 20 FEET <sup>EAST</sup> OF FENCE → N20°E & S20°W.

Signature Tennis L. Hayward Title PLS Division 1636 Headquarters S.O. Date APRIL 12, 1991 FS-7100-52 (3/88)

**CORNER RECORD (PERPETUATION)**

**MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT**

**ACCESSORIES : DESCRIBE NEW BT<sup>1</sup>/<sub>2</sub> WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE**

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. \_\_\_\_\_  
or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor.