

Index

File No. E-13

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____


Cor.

No. _____

T 3N R. 38ER.D. WALLA WALLA County UNIONMerid. WILLAMETTEN.F. UMATILLA State OREGON

CORNER DIAGRAM

T3N R38E



DESCRIBE CORNER MONUMENT FOUND

CORNER STONE IS SOLIDLY SET & VERY PLAINLY MARKED WITH 3 GROOVES ON THE EAST FACE & 5 GROOVES ON THE SOUTH FACE. A SUBSTANTIAL MOUND OF STONES IS ALONG THE WEST SIDE OF STONE. ²

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE - NONE WERE SET.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature ⁷

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency ⁸

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

Dennis L. Hayford PLS 1636

SIO.

10-14-1993

³⁴⁵

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor.