

USDA-FOREST SERVICE

Index  
File No. X-13  
T 3S R. 31E  
Merid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. Ukiah County Umatilla  
N.F. Umatilla State Oregon  
Tract or Survey No. Sec 34 Cor. No. W 1/4

CORNER DIAGRAM

T3S R31E  
1/4  
S33 | S34



DESCRIBE CORNER MONUMENT FOUND

None.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 23" dia Fir Stump bears N85°W 40.26 ft dist (old BT) found scribing inside healed blaze in bucked off piece next to stump. An old rotten Fir bears East - 22 ft+ dist (old BT) The old rotten Fir's original position could not be determined.

PHOTO IDENTIFICATION DATA

Photo No. 616140 380-4  
Filed At Umatilla Nat. Forest  
Object Ident. Trees  
Ident. By \_\_\_\_\_  
*Signature*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Yellow Jacket Road South to road #5420, then South to Road #5412-100, then West approx. 2 miles to road heading South, then through gate and follow road approx. 0.3 mile to road heading South and West, then 3/4 mi to road turning North, then North approx. 0.2 mile to top of crest, then W approx. 200 ft West of road, in old Skid Trail to corner, timbered.

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_  
*Agency*

Signature William R. Wells Title PLS 1106 Division \_\_\_\_\_ Headquarters \_\_\_\_\_ Date October 6, 1982 7100-52-(3/68)

**CORNER RECORD (PERPETUATION)**

**MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT**

Set 2 1/2" brass cap on 2 1/2" x 30" l. pipe 15" in ground with mound of stone.

Set steel fence post with 54-4 sign attached, North of corner. Cap marked:

T3S R31E  
1/4  
S33 | S34  
1982  
PLS 1106

**ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE**

A 9" dia Grand Fir bears N43°E 27.1 ft dist marked: 1/4 S34 BT.

A 11" dia Grand Fir bears N70°W 41.5 ft dist marked: 1/4 S33 BT.

Blaze faces and 6" bands around bearing trees are painted red. Tagged trees with 54-3 & 4 signs.

New BTs have a lower blaze, scribed BT, with a brass washer stamped PLS 1106 nailed flush.

Work Done By. W.R. Wells Title Surveyor Date 10/6/82 State Registration No. or Agency PLS 1106

Certified Cor. Record Prepared? Yes  No  Filed At: Umatilla County Surveyor Office Date \_\_\_\_\_

**REMARKS**

Witnessed by: D.L. Kaufman PLS  
R.D. English PC  
L. E. Wilson  $\phi$   
L. D. Henshaw  $\phi$

USDA-FOREST SERVICE

Index

File No. X-13

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. \_\_\_\_\_

Cor. \_\_\_\_\_

No. \_\_\_\_\_


T 3S R. 31E

R.D. UKIAH County UMATILLA

Merid. WILL

N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE - SEARCH AREA HAS BEEN INTENSIVELY LOGGED.

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PROCEEDED FROM <sup>28127</sup>/<sub>33134</sub> WITH HAND COMPASS & HIP CHAIN. CREEK CALL AT 73.5 CHAINS FITS GOOD. REMAINS OF AN ANCIENT FENCE FOUND IN SEARCH AREA (N-S FENCE).

Signature

Title

Division

Headquarters

Date

7100-52-(3-68)

Dennis L. Hayward

PLS 1636

3-11-81

**CORNER RECORD (PERPETUATION)**

**MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT**

9

**ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE**

10

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No.  
or Agency \_\_\_\_\_

Certified Cor. Record Prepared? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

11

**REMARKS**

12

Index File No. T. R. M. Tract or Surv. No. Cor.

13

Index  
File No. X-13


**CORNER RECORD (SEARCH)**

Tract or  
Survey No. 5-61 Cor. No. X-13

T 3S R. 31E R.D. Ukiah County Umatilla

Merid. Willamette N.F. Umatilla State Oregon

**CORNER DIAGRAM**



**DESCRIBE CORNER MONUMENT FOUND**

Material: None.

**DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND**

None. Could find no evidence.

**PHOTO IDENTIFICATION DATA**

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

*Signature*

**PLANE COORDINATE POSITION DATA**

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

*Agency*

**DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER**

A primitive road runs north-south, about 200 feet east of approximate corner location.

Signature:  
T. Hollamon

Title  
Engineering Technician

Division

Headquarters  
S,O.

Date  
November 21, 1974

7100-52  
REV. 65 5

**CORNER RECORD (PERPETUATION)**

**MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT**

9

**ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE**

10

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

11

**REMARKS**

12

Index File No. T. R. M. Tract or Surv. No. Cor,

13