

Index

File No. X 9

T 3S R. 33E

Merid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. La Grande

N.F. W-W

County Union

State Oregon

Tract or


Survey No. _____

Cor.

No. W 1/4 Cor

Sec 33

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

30" sawed PP stume bears S. 75° W. 61 lks. down and decayed
 13" DF bears N. 65° E 40 lks.

The stump is decayed down to pitch but I chopped into the bottom blaze on the DF and uncovered the BT and left the the upper blaze intact. The evidence here is rather fragile.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

I posted the road about S. 60° E. 29 chains up along the ridge I believe the way to come in here is down the ridge past an old log cabin which is about 1/4 mile S. 60° E. from the corner. Corner is located about 2 chains NE of the top of the ridge.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature
John Mitchel

Title _____

Division _____

Headquarters _____

Date
9/21/76

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____


Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor.

Index File No. X 9 CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. _____ Cor. No. W 4 Cor. Sec 33
 T 3S R. 33E R.D. La Grande County Union Merid. Willamette N.F. W-W State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

30" sawed PP stume bears S. 75° W. 61 lks. down and decayed
 13" DF bears N. 65° E 40 lks.
 The stump is decayed down to pitch but I chopped into the bottom blaze on the DF and uncovered the BT and left the the upper blaze intact. The evidence here is rather fragile.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

I posted the road about S. 60° E. 29 chains up along the ridge I believe the way to come in here is down the ridge past an old log cabin which is about 1/4 mile S. 60° E. from the corner. Corner is located about 2 chains NE of the top of the ridge.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
Agency

Signature
 John Mitchel

Title

Division

Headquarters

Date
 9/21/76

7100-52-(3.68)

UNION COUNTY SURVEYOR

Date Received _____

Date Filed 12-21-87

By G. LANGLITZ, Deputy

File No. 271-87R

6-X