

OREGON CORNER RESTORATION FORM

Section 32 Township 4N Range 29E Index X7

County Umatilla Date 5/05/95

CORNER DESIGNATION:

C1/4

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed
 Reference

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)
 Found 2 1/2 " Umatilla County Surveyor brass cap in north lane of
 Harding Street and east edge of Dunne Street.

Monument Detail	Sketch
T4N	
R29E	
C1/4	
S32	
1974	
PLS 933	

Monument Set (Procedures and Description)

New Accessories


Tied to existing features:
 Center of manhole bears N86°41'W, 61.7'.
 Umatilla County Surveyor reference monument bears N5°48'W, 20.56'.
 Galvanized pipe street sign bears S3°38'W, 33.45'.

Location & Comments


In Stanfield, go to the
 intersection of E. Harding
 and N. Dunne.

Compass Declination 20°
 Firm/Agency
 Haddock Surveying
 Address P. Box 1574
 Pendleton, OR 97801
 Party Chief D. Haddock
 Notes
 Witness S. Haddock

Surveyor's Seal



David L. Haddock



RECEIVED BY

Umatilla County Surveyor
 Date 6-95
 Rec'd By KB
 No. 95-104-R