

Index

File No. T-16

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. _____

T 4N R. 38E

R.D. WALLA WALLA County UMATILLA

Merid. WILLAMETTE

N.F. UMATILLA State OREGON

CORNER DIAGRAM



T4N R38E

C E 1/16 C

S 27

1980

RLS 934

DESCRIBE CORNER MONUMENT FOUND

2 1/2" BRASS CAP ON A 2 1/2" GALV. IRON PIPE WITH CAP SET FLUSH IN A MOUND OF STONE. MOUND IS IN EXCELLENT CONDITION.

THIS CORNER WAS ESTABLISHED AS PART OF SURV. NO. R-176-G.²

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 8" DOUGLAS FIR BEARS N60°E 96.4' WITH PARTLY HEALED DOUBLE BLAZE. (SURV. NO. R-176-G).

A 10" DOUGLAS FIR BEARS S58°E - 146.9' WITH PARTLY HEALED DOUBLE BLAZE. (SURV. NO. R-176-G).

BEARING TREES ARE TAGGED WITH SIGN 54-3 AND 54-9.³

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER IS LOCATED ON THE WEST SIDE OF A NORTH-SOUTH RIDGE. GROUND BREAKS STEEPLY JUST WEST OF CORNER. WALK TO CORNER FROM ROAD ABOUT 900' TO EAST.

Signature

Walter R. Webb

Title

PLS

Division

Headquarters

PENDLETON

Date

12-6-91

FS-7100-52 (3/88)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET OR WORK DONE TO PRESERVE EXISTING MONUMENT

CORNER MONUMENT AND ACCESSORIES ARE IN GOOD SHAPE AND NO MAINTENANCE WAS PERFORMED. THERE IS A STEEL FENCE POST SET NEAR CORNER WITH SIGNS 54-2 AND 54-9 ATTACHED

ACCESSORIES DESCRIBE NEW BT^{1/2} WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By VLR WELLS Title PLS Date 12-9-60 State Registration or Agency 106

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T-16 T. 4N R. 38E M. WILLAMETTE Tract or Surv. No. _____ Cor. _____