

USDA-FOREST SERVICE

Index File No. E-23

T 45 R. 30E

Merid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. Ukiah

County Umatilla

N.F. Umatilla


State Oregon

Tract or Survey No. _____

Cor. No. _____

2-3

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND Searched for corner near midpoint between Sec. Corner. No evidence found. N-S fence runs through position of corner; stone has probably been moved into a fence jack.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

No bearing tree evidence found. An old fire has destroyed any traces; therefore, the position of the corner is determined by proportion.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is on a level bench approx. 100 ft. West from primitive road, coursing NW at a point approx. 350 ft. SE from a NE, SW, SE road junction.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estob. By _____
 Agency _____

Signature _____

Title _____
 PLS 848

Division _____

Headquarters _____
 Mt. Vernon, OR

Date _____
 8/14/81

7100-52-(3.68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 3"x30" galv. iron pipe with 3" brass cap stamped as shown in the diagram, set 16 inches in the ground and raised a mound of stone and earth around the pipe.

From which:

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A pine 15 in. dia. bears S 13°E, 91.5 ft. scribed 1/4 S 12 BT.
A pine 11 in. dia. bears N25°E, 2.8 ft. scribed 1/4 S 1 BT.
Set steel post with warning sign, N15°W, 5 ft. from corner.
N-S fence, 2 ft. East from corner.
Nailed bearing tree signs and brass washers stamped PLS 848 to each tree.
Painted red band around each tree.

Work Done By D.M. Ferguson Title Surveyor Date 8/14/81 State Registration No. OR PLS 848
or Agency

Certified Corner Record Prepared Yes No Filed At: Umatilla Co. Surv. Off. Date 10/81

REGISTERED
PROFESSIONAL
LAND SURVEYOR

REMARKS

Witnesses to above corner:
D. Mitchell Ferguson
Mike Woodward

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

USDA-FOREST SERVICE

Index File No. E-23

T 4S R. 30E

Merid. Willamette

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

R.D. Ukiah County Umatilla

N.F. Umatilla State Oregon

Tract or Survey No. _____ Cor. No. _____

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Burned stumps in area. Fence line does not fit soc. line as shown on quad. map. (Fence east and north).

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Bill Moore

Title

Eng. Tech.

Division

Headquarters

Date

4/78

7100-52-(3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No.
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. 12 13