


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.



H-21

Description of corner evidence found:

N/A

Description of monument and accessories established to perpetuate the original location of this corner:

Set 3"x30" galv. iron pipe with 3" brass cap stamped as shown on the diagram, set 12 inches in the ground and raised a mound of stone and earth around the pipe.
No bearing trees are available.
Set steel posts with warning and boundary signs 5 ft. South and 5 ft. East from corner.

I hereby certify that the above corner monument was established as herein described on 8/4/81.

Witnesses: D. Mitchell Ferguson

Mike Woodward

REGISTERED
PROFESSIONAL
LAND SURVEYOR

[Signature]
OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Office of Co. Surveyor County of Umatilla
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 7th day of January, 1982
David Krumbein by Betty Shatt
(COUNTY OFFICIAL) (DEPUTY)

82-01-C