

OREGON CORNER RESTORATION FORM

Z-1

SECTION 31, 36 TOWNSHIP 5 NORTH, RANGE 29 EAST, RANGE 28 EAST

COUNTY : UMATILLA DATE DEC/22

CONDITION REPORT ONLY

CORNER DESIGNATION

NOT FOUND

SECTION CORNER

RENEWED

UNCOVERED

SURVEYED IN

PREVIOUS RENEWALS / SURVEYS, ETC.

REFERENCED

SURVEYED IN 1860 BY MAXON AND HURD UNDER CONTRACT #50, THEY SET POST AND MADE MOUND.
IN 1910 KIMBRELL FOUND CORNER.
IN 1978 LAGIER SET 5/8" IRON ROD.
IN 1980 KRUMBEIN SET 2 1/2" BRASS CAP.
IN 1984 CRAMER SET RIAL ROAD SPIKE.
IN 1997 ROBERTS COMPUTED LOCATION.
IN 2005 LS 951 SET 2" ALUMINUM CAP.

MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

FOUND 2" ALUMINUM CAP DEFACED.
FOUND 5/8" IRON ROD WITH YELLOW PLASTIC CAP STAMPED LS 951 BEARS S 24°11'45" W, 17.69'.
FOUND 5/8" IRON ROD WITH YELLOW PLASTIC CAP STAMPED LS 951 BEARS S 69°31'02" E, 99.53'.
FOUND 5/8" IRON ROD WITH YELLOW PLASTIC CAP STAMPED LS 951 BEARS N 66°38'01" W, 87.58'.
FOUND 5/8" IRON ROD N 66°27'02" E, 12.64'.
FOUND 2 1/2" BRASS CAP N 41 E, 13.9' (NOT EXPOSED).

MONUMENT DETAIL



NAD 83/91
OREGON STATE PLANE
INTERNATIONAL FEET

803764.96
8521857.25

MONUMENT SET (PROCEDURES AND DESCRIPTION)

NEW ACCESSORIES FROM WHICH

LOCATION AND COMMENTS

CORNER FALLS AT THE INTERSECTION
OF NORTH OTT ROAD AND PUNKIN
CENTER ROAD.

FIRM/AGENCY

PRIMM LAND SURVEYING, INC.
P.O. BOX 1322
HERMISTON, OREGON 97838

SURVEYOR'S SEAL

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 13, 1999
BRIT L. PRIMM
48509

LAND SURVEYOR

BRIT L. PRIMM

WITNESS

KEITH P. PRIMM

EXPIRATION DATE: 12/31/24