

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

W-16

History of original corner establishment:

Original corner position determined by Bureau of Land Management survey performed during 1967-1980.


Set an iron post, 28 ins. long, 2 1/2" diam., 24 ins. in the ground, with brass cap marked:

NE 1/16 S 34
1968

from which:

A Pine, 7 ins. diam., bears S 11 1/2°E
22 lks., mkd. NE 1/16 S 34 BT.

A Pine, 8 ins. diam., bears S74°W 46 lks. dist., mkd.
NE 1/16 S 34 BT.



Description of corner evidence found:

The corner monument and accessories were found in good condition as described in the BLM record with the following exception:

The species of the SW bearing tree is Douglas Fir.

Description of monument and accessories established to perpetuate the original location of this corner:

August 22, 1984

Witnesses:

Gary Langlitz, LS 1099
Ray Crapo
Greg Orton



Office of Surveyor County of Umatilla
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 22 day of October, 1984
David Rumbert by Betty Coakley
(COUNTY OFFICIAL) (DEPUTY)