

Index
File No. X-18

CORNER RECORD (SEARCH)
(Ref. FSM 7.151.4)

Tract or
Survey No. _____
Cor.
No. _____

T 5S R. 32E

R.D. UKIAH County UMATILLA

Merid. WILLAMETTE

N.F. UMATILLA State OREGON

CORNER DIAGRAM

W 1/16
C _____ C
Sec. 35
T5S R32E



DESCRIBE CORNER MONUMENT FOUND
Found a 2 1/2" dia. iron pipe, set as
described in the Official BLM
Record, with brass cap attached,
marked

U.S. Dept. of Interior
Bureau of Land Management
W 1/16
C _____ C
S 35
1968 ²

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
A 14" Douglas Fir, alive and well-healed. Bears S 46°E 25.1 feet.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER. ³

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estate By _____
Agency

Signature of Larry J. Sample

Title LS 1099 Division _____ Headquarters _____ Date 7-17-84 ⁴
FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

An 8" Douglas Fir, scribed "CW 1/16 S35 BT" on a double blaze bears S 40°W 66.1 feet. Attached brass washer marked "LS 1099" to lower blaze.

Work Done By Gary Langlitz Title LS 1099 Date 8-84 State Registration No. or Agency

Certified Cor. Record Prepared? Yes No Filed At UMATILLA CO. SURVEYOR Date 9-84

REMARKS

Corner of fences S and W bears 70' South and 80' West.
Magnetic Compass, (Declination 20° East)
Steel Tape
August 15, 1984

Index File No. X-18 T. 55 R. 32 E M. WILLAMETTE Tract or Surv. No.

Cor. No.