

Index File No. X-6

CORNER RECORD (SEARCH)
(Ref. FSM 7.151.4)

Tract or Survey No. _____ Cor. No. _____

T 5S R. 32E

R.D. UKIAH County UMATILLA

Merid. WILLAMETTE

N.F. UMATILLA State OREGON

CORNER DIAGRAM

W 1/16
C _____ C
S 32
1980

DESCRIBE CORNER MONUMENT FOUND

Found an iron pipe, firmly set, 2½ ins. diam., in a mound of stone, 3 ft. base, to top, with brass cap mkd.

U.S. Dept. of Interior
Bureau of Land Management
W 1/16
C _____ C
S 32
1980

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A Ponderosa Pine, 14 ins. diam., bears S: 47° E., 136½ lks. dist.,
Found a mound of stone, 3 ft. base, 1½ ft. high, N. of corner.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

Harry J. Knight

Title LS 1099 Division _____ Headquarters _____

Date 9-17-84 FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

We mark an additional BT:

A 6" Ponderosa Pine, scribed "CW 1/16 S32 BT" on a double blaze, bears S 10°W 94.6 ft., attached brass washer marked "LS 1099" to lower blaze.

10

Work Done By Gary Langlitz Title LS 1099 Date 8-84 State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: UMATILLA CO. SURVEYOR Date 9-84

11

REMARKS

Corner is located 6 ft. West of a N-S fence.

August 30, 1984
Magnetic Compass
20° East Declination
Steel Tape

12

Index File No. X-6 T. 55 R. 32 E M. WILLAMETTE Tract or Surv. No. Cor. _____

13