## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

No corner was originally set.

Index File No. D-23

DIAGRAM

T5S R33E S 1/16+S1

Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 2½"x30" galvanized pipe with brass cap stamped:

Set pipe 24" in ground with mound of stone to cap.

Bearing Trees:

A Tamarack 5" dia., bears S64°E, 31.3 ft., scribed CS 1/16 S1 BT.

A Tamarack 7" dia., bears N60°E, 16.4 ft., scribed CS 1/16 S1 BT.

T5S R33E 1980 OR PLS 1294

Attached 54-3 and 54-4 signs to both BTs. Attached brass washer stamped LS 1294 to foot blaze of both BTs. Painted blazes and 6" band around both BTs Red. Attached 54-2 and 54-4 signs to metal post 6 ft. East of corner. Attached 54-2 and 54-9 signs to wood post 12 ft. South of corner.



I hereby certify the above corner monument was established as herein described on June 18, 1980.

Witnesses: R. Orton

G. Orton

D. Allen

Office of County Surveyor	County of Umatilla
State of Oregon / hereby certify the	t the within instrument was filed in this office
for record on the day of flesentile.	J 1880.
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

☆ GPO-798-276