## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: No corner was originally set.

Index File No. H-24

DIA	GRAM
T5S	R33E
SE 1/16	S12

Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner: At surveyed point set 2 1/2"X30" galvanized pipe with brass cap stamped: Set pipe 24" in ground with mound of stone to cap.

A Lodge Pole Pine 8" dia bears N45°E, 26.2 ft., scribed SE1/16 S12 BT. A Tamarack 18" dia bears S24°W, 47.0 ft., scribed SE1/16 S12 BT.

Attached 54-3 & 54-4 signs to both BTs. Attached brass washer stamped LS 1294 to foot blaze of both BTs. Painted blazes and 6" band around both BTs Red. Attached 54-2 & 54-4 signs to metal post 5 ft west of corner. Attached 54-2 & 54-9 to metal post 5 ft south of corner.



I hereby certify the above corner monument was established as herein described on July 8, 1980.

Witnesses: R. Orton L. Huntsman

D. Allen

Office of County Surveyor	County of Umatilla
	fy that the within instrument was filed in this office
David Friende	by Betty Shalts

Form R6-7100-57 (9/71)