


USDA-FOREST SERVICE

Index
 File No. L-21
 T 5S R. 33E
 Merid. Willamette

CORNER RECORD (SEARCH)
 (Ref. FSM 7151.4)

R.D. Ukiah County Umatilla Tract or Survey No. _____ Cor. No. 1/4
 N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

No evidence of original corner post could be found.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Found Fir 14" dia. with healed over blaze on S.W. side of tree. Opened blaze and found visible scribing "1/4 S". Found old stump hole and rotted pieces of southwest BT.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner falls on north slope. Take U.S.F.S. Road No. 5440 south off of State Hwy. No. 244 to location tag on SE side of road. Walk north approximately 200 feet to corner.

Title _____ Division ORLS Headquarters 1294 Date 9/77
 7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT	T5S R33E
At record bearing and distance from found N.E. BT. Set 2½"x30" galvanized pipe with brass cap stamped:	1 — 4
Set pipe 24" in ground with mound of stone to cap.	S14 — S13
	1980 OR PLS 1294

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

From which:

Old BT: A Fir 14" dia. bears N70⁰E, 23.8 ft., with visible scribing "1/4 S".
 New BT: A Tamarack 10" dia. bears N51⁰W, 21.1 ft., scribed 1/4 S14 BT. Attached 54-3 and 54-4 signs to both BTs. Attached brass washer stamped LS1294 to foot blaze of new BT. Painted blazes and 6" band around both BTs. Attached 54-4 sign to metal post 5 ft. north of corner.

10

Work Done By	R.C. Orton	Title	Party Chief	Date	6/23/80	State Registration No. or Agency
Certified Cor. Record Prepared ?	Yes	No	Filed At:	Date		

11

REMARKS

Witnesses: R. Orton
 G. Orton
 D. Allen

Index File No.	T.	R.	M.	Tract or Surv. No.	U.S. G.P.O. 1977-725-576/586
L-21	SS	33E			13

Index

File No. L-21

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.


No. L-21

T 5 S R. 33 E

R.D. Ukiah County _____

Merid. _____ N.F. Umatilla State _____

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Material; None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

14" Fir--NE Quad.--with upper and lower SW blaze.
(Tree was 7" when scribed). Needs opening to verify.

Rotten stump SW Quad. approx. where other BT would be.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

6-13-79

Signature

B. Moore

Title _____

Division _____

Headquarters _____

Date _____

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

I placed B.T's and attention poster on the assumed bearing tree 100' North of Rd. 5440.

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. U.S. G.P.O. 1977-725-576/586