


F-9

History of original corner establishment:

No previous history of this corner.



Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

I set a 2 1/2" brass cap on a 30" galv. iron pipe and being stamped as shown in the above diagram, and having a large mound of stone placed around the monument.

New bearing trees:

A pine 5" dia. bears S 62 W, 41.98 feet and scribed 1/16 S 8 BT.
A pine 6" dia. bears S 53 E, 62.94 feet and scribed 1/16 S 9 BT.

REGISTERED PROFESSIONAL LAND SURVEYOR

James H. Hambleton
8-21-78

OREGON JULY 10, 1964 JAMES H. HAMBLETON 645

I hereby certify the above corner monument was re-established as herein described in August 1978.

Witnesses: *James E. Shaw* Crew Chief
[Signature] Instrument/Man

H-9

Office of..... County of.....
State of..... I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....
..... by
(COUNTY OFFICIAL) (DEPUTY)

73-39-B