

USDA-FOREST SERVICE

Index

File No. A-23

T6S

R30E

Merid. Willamette

R.D.

N.F.

CORNER RECORD (SEARCH)

Ref. FSM 7151.4

North Fork John Day

Umatilla

Tract or

Survey No

County

State

Cor.

No.

Umatilla

Oregon

x

Corner Diagram T6S R30E

1/4 S1

CC

1977

PLS 933

1

1 Describe corner monument found

1 Steel pipe extending 2" above the ground with a 2 1/2" brass cap stamped as shown in the diagram.

1

1

1

1

1

x

Photo Identification Data

Photo No. 1487-58

filed at Pendleton, OR

Object Ident. bearing trees

Ident. by D. Haddock

Signature

1

1 Describe bearing trees or other official accessories found

1 A 21" Douglas Fir bears S68°28'E, 23.0' scribed T6S R30E 1/4 S1 BT.

1 A 29" Ponderosa Pine bears S73°28'W, 55.7' scribed T6S R30E 1/4 S1 BT.

1

1

1

1

x

Plane Coordinate Position Data

State Zone

X

Y

Estab. by

Agency

1

1 Describe corner location relative to near-by features, also how to reach corner

1 From the junction of roads 5312 and 5320, follow 5320 east 1.6 miles to road

1 5320110. Then follow road 5320110 east 1.9 miles to the end of the improved rock

1 road. From the end of this road, walk down the hill east along the posted line

1 approximately 150' to the corner.

1

1

x

Signature

David L. Haddock

Title

Land Surveyor

Division

Headquarters

Pendleton, OR

Date

June 1988

7100.52

CORNER RECORD (PERPETUATION)

X-----X  
 Monument: Describe new monument set, or work done to preserve existing monument

*TRUE CORNER POINT*

Set steel guard post 5' west of the ~~monument~~ and attached Forest Service Land Survey Monument and Property Boundary signs.

X-----X  
 Accessories: Describe new BT's witness objects etc. established, or work done to preserve existing evidence

Made bands around trees and painted the bands and the scribes red. Attached Forest Service Land Survey Monument signs to the trees.

X-----X

Work done by	David L. Haddock	Title	Land Surveyor	Date	Nov 1988	State Registration No.	
Certified cor. record prepared?	yes		no x	Filed at		or Agency	852
						Date	

X-----X  
 REMARKS

X-----X  
 Index File No.    A-23    T.6S.    R.30E.    M. Willamette    Tract or Survey No    Cor.

USDA-FOREST SERVICE

Index  
File No. A-23  
T 6S R. 30E  
Merid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or  
Survey No. \_\_\_\_\_ Cor.  
No. \_\_\_\_\_

R.D. Ukiah County Umatilla  
N.F. Umatilla State Oregon

CORNER DIAGRAM



T. 5S., R. 30E.

1/4 S.1

CC

T. 6S., R. 30E.

DESCRIBE CORNER MONUMENT FOUND

None

*Set brass cap*

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
Filed At. \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By: \_\_\_\_\_  
*Signature*

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_  
*Agency*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From the intersection of U.S. Forest Road 419N and 537N, go East along 537N 1.8 miles to Gulliford crossing, then 2.1 miles East, then corner is 130 ft. North of road.

*Signature*  
*David H. Kline*

Title \_\_\_\_\_ Division \_\_\_\_\_ Headquarters \_\_\_\_\_

*OPLS*

*933*

Date

*7-77*

7100-52-(3/68)

## CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

T. 6S., R. 30E.

Set 2½" x 30" iron pipe with brass cap.

Pipe is 28" in ground.

Stamped:

¼ S.1

CC

1977

PLS 933

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 21" fir bears S. 68°28' E. 23.0 ft.

A 29" pine bears S. 73°88' W. 55.7 ft.

Set steel post 3 ft. East w/sign.

Painted red band around BT trees w/sign.

10

Work Done By T. Hamby Title Party Chief Date 6/23/77 State Registration No. \_\_\_\_\_  
or Agency \_\_\_\_\_Certified Cor. Record Prepared? Yes  No  Filed At: \_\_\_\_\_ Date \_\_\_\_\_

11

REMARKS

12

Index File No.

T.

R.

M.

Tract or Surv. No.

Cor.

13