

USDA-FOREST SERVICE

Index
File No. B-19

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or
Survey No. _____ No. _____

T 6S. R. 30E. R.D. Ukiah County Umatilla

Merid. Willamette N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None

Set brass cap

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From intersection of U.S. Forest Road 419N and 537N, go South by East about 2.6 miles, then turn left and go 0.3 miles, then walk North 10.00 chns. to corner.

Signature
David H. Kline

Title

Division

Headquarters

Date

OPLS

933

7-77

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

GPO 902-673

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½" x 30" iron pie with brass cap.
Pipe is 26" in ground.

C
N. 1/16 S.2

Stamped:

C
1977
PLS 933

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 11" fir bears S. 82°20' W. 14.3 ft.
A 7" fir bears S. 80°47' E. 14.0 ft.

Set steel fence post 2 ft. East of corner w/sign.
Painted red band around BT trees w/sign.

Work Done By R. T. Hamby Title Party Chief Date 6/23/77 State Registration No. _____
or Agency _____

Certified Cor. Record Prepared? Yes No _____ Filed At: _____ Date _____

REMARKS