


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner

Set 32" X 2" flanged iron pipe with brass cap marked:
From Which

T6S R30E
0 $\frac{1}{4}$ S6
1979
PLS 346

Ponderosa Pine, 10" Dia., BRS. S65 $\frac{1}{2}$ ⁰E., 23.2 Ft. Dist.
Marked: 0 $\frac{1}{4}$ S6 BT

Douglas Fir, 12" Dia., BRS. N44 $\frac{1}{2}$ ⁰W., 49.4 Ft. Dist.
Marked: 0 $\frac{1}{4}$ S6 BT

6' iron fence post with "Survey Monument" sign within 5' of corner

All B.T. have Bt tag and painted red stripe. New BTs have Brass Washer stamped:
PLS 346; nailed to lower blaze.

Office of County Surveyor County of Umatilla
 State of Oregon, I hereby certify that the within instrument was filed in this office
 for record on the day of
 _____ by _____
 (COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

RECEIVED BY
Umatilla County Surveyor
 Date 10-17-79
 Rec'd By ymj
 No. Q-1171-B

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

 OREGON
 MAY 6, 1955
 WAYNE O. HARRIS
 346

C-3