

USDA-FOREST SERVICE

Index
File No. E-13

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or Survey No. _____
Cor. No. _____

E-13

T 65 R. 30E R.D. UKIAH County UMATILLA
Merid. WILLAMETTE N.F. UMATILLA State OR

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Fd BASALT STONE 17"X12"X9" MKD WITH 3 NOTCHES ON W
EDGE & 5 GROOVES ON S. FACE.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A DEAD & DOWN 14" PINE BR5 N59°E 50.8 FT MKD BT.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

COR IS 12 FT EAST OF N.S. FENCE

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature

RD Baggett

Title

LAND SURVEYOR

Division

Headquarters

Date

9-30-76

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" x 30" IRON PIPE w/ BRASS CAP MKD

T65R30E

34 | 53

39 | 510

1976

OPL55A8

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

NEW BT'S

A 8" FIR BR5 N27°E 222 FT MKD T65R30E S3BT

A 27" PINE " S84°E 403 " " T65R30E S10 BT

A 8" FIR " S9°W 252 " " T65R30E S9BT

A 12" PINE " N67°W 37' " " T65R30E S4BT

10

Work Done By. R.D. Baggett Title LAND SURVEYOR Date 9-30-76 State Registration No. OPL55A8
or AgencyCertified Cor. Record Prepared? Yes No Filed At: UMATILLA C.S. Date 11

REMARKS

Index File No. E-13 T. R. M. Tract or Surv. No. Cor. 12 13