

Index  
File No. C-5  
T 6S R. 31E  
Merid. \_\_\_\_\_


CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or  
Survey No. \_\_\_\_\_ No. C-5

R.D. Ukiah County Umatilla  
N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Pine 21" DBH bearing N17 W 76 IKS has a good visible unmistakable scar, painted a 6" red band and painted scars. Put proper tags on it, a bearing tree tag and an attention sign. Found a pine bearing S85 E 30 links in very poor cond. with some visible scribing in top scar. Tree has been burned. Painted scars and 6" red band around tree. Put two posts up with two signs on each

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
Filed At. \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By \_\_\_\_\_  
*Signature*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estob. By \_\_\_\_\_  
*Agency*

Signature  
MLC

Title  
For, Tech,

Division  
USFS

Headquarters  
Ukiah

Date  
4/20/78

7100-52-(3,68)