


LAND CORNER RECORD

5680-2

1. T 6S R 32E No. E19 Cor. 1/4 Mer. Will. State Oregon N.F. Umatilla Dist. Ukiah

2. Corner Status



3. Original Description Vol. _____ Page _____ Where Recorded Ukiah P.D.

4. Description of Corners: Tamarack post 3" square 3' long
A tamarack 24" dia. br. S. 79° W. 50 lks.
A tamarack 8" dia. br. N. 52° E 30 lks.

~~See map of Brass Cap.~~ Monument Removed by BLM 1982

5. Investigation Notes:

B.T. Western Larch 1 1/2" dia., good vigor, scribing visible
Form 54-3 present
placed form 54-4

7. Photo Identification

Photo No. _____
 Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Field Book No. _____
 Where Filed _____

9. Evaluation

Authentic _____
 Needs Verif. _____ Monument _____
 Re-estab. _____ Survey _____
 Land Status _____

6. Signed K.R. Johnson Title Forester Date 6-9-66

PERPETUATION RECORD

10. Monument :

11. Accessories

Field Book _____ Page _____

12. Set By _____ Title _____

License _____ Agency _____ Date _____

13. Recorded By _____ (Agency) _____ Volume _____ Page _____

(Date) (City) (County) (State)

14. Remarks:

E-19