

USDA-FOREST SERVICE

Index
File No. R-19

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____
Cor. No. _____

T 68 R. 32E

R.D. N. Fk. J. Day County Umatilla

Merid. W.M.

N.F. Umatilla State Or.

CORNER DIAGRAM



$\frac{1}{4}$ $\frac{823}{826}$

DESCRIBE CORNER MONUMENT FOUND

$2\frac{1}{2}$ " iron pipe with brass cap mkd.
in stone mound.

T68 R32E
 $\frac{1}{4}$ $\frac{823}{826}$
1968

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

W. Fir, 17", N51°E, 59.4', with scribing visible
D. Fir, 13", S80°E, 89.1', with healed blaze

PHOTO IDENTIFICATION DATA

Photo No. 280-242

Filed At. S.O.

Object Ident. trees

Ident. By F.S. Munro

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

F.S. Munro

Title

L.S.

Division

Headquarters

Date

11/19/86

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None..

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BTs have blaze and 6" hand painted red., BT tags and "Attention" signs.
6' steel fence post with "Attention" sign within 5' of the corner.

10

Work Done By. F.S. Munro Title L.S. Date 11/1/86 State Registration No. 1832
or Agency

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. R-19 T. 6S R. 32E M. W.M. Tract or Surv. No. _____ Cor. _____

13