

## USDA-FOREST SERVICE

Index

File No. S-13

T6S

R32E

Merid. Willamette

R.D.

N.F.

CORNER RECORD (SEARCH)

Ref. FSM 7151.4

North Fork John Day

Umatilla

Tract or

Survey No

County Umatilla

State Oregon

Cor.

No.

x

Corner Diagram

1

N--

16

S28 1 S27

1979

x

Photo Identification Data

Photo No.

filed at

Object Ident.

Ident. by

Signature

x

Plane Coordinate Position Data

State

Zone

X

Y

Estab. by

Agency

x

Signature

Title

Division

Headquarters

Date

7100.52

David C. Haaslock

Land Surveyor

Pendleton, OR

July 1988

CORNER RECORD (PERPETUATION)

X \_\_\_\_\_ X  
 Monument: Describe new monument set, or work done to preserve existing monument

Set steel guard post 5' south of the monument and attached Forest Service Land Survey Monument and Property Boundary signs.

x \_\_\_\_\_ x  
 Accessories: Describe new BT's witness objects etc. established, or work done to preserve existing evidence

Made bands around trees and painted bands and scribe blazes red. Attached Forest Service Land Survey Monument and Bearing Tree signs to the trees.

x		x	
Work done by	David L. Haddock	Title	Land Surveyor
Certified cor. record prepared?	yes	no	x
		Filed at	Date
			July 1988
			State Registration No.
			or Agency
			Date
			852

x \_\_\_\_\_ x  
 REMARKS

x \_\_\_\_\_ x