

Index  
File No. U-11  
T 68 R. 32E  
Merid. W.M.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. N. Fk. J. Day County Umatilla Tract or Survey No. \_\_\_\_\_ Cor. No. \_\_\_\_\_  
N.F. Umatilla State Or.

CORNER DIAGRAM



081/16 S28

DESCRIBE CORNER MONUMENT FOUND

2 1/8" iron pipe with brass cap mkd.  
in stone mound.

S1/16 |  
C  
C  
1968

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

D. Fir, 19", N57 1/2° E, 67.3', with scribing visible  
P. Pine, 9", S54° W, 57.4', " " " "

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
Filed At. \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By \_\_\_\_\_  
*Signature*

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estob. By \_\_\_\_\_  
*Agency*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner falls on rocky south slope north of 55 rd.  
and visible from rd.

*Signature*  
F. J. Munnis

Title  
L.S.

Division

Headquarters

Date  
11/19/86

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None..

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BT's have blaze and 6" band painted red, BT tags and "Land Survey Monument" signs. 6' steel fence post with "Land Survey Mbnument" sign within 5' of the corner.

Work Done By. F.S. Munro Title L.S. Date 11/2/86 State Registration No. 1832 or Agency  
Certified Cor. Record Prepared ? Yes No  Filed At: \_\_\_\_\_ Date \_\_\_\_\_

REMARKS

Index File No. U-11 T. 6S R. 32E M. W.M. Tract or Surv. No. \_\_\_\_\_ Cor. \_\_\_\_\_