

USDA-FOREST SERVICE

Index File No. X-23

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____

T 6S R. 32E R.D. NORTH Fork JOHN DAY County UMATILLA

Merid. WILLAMETTE N.F. UMATILLA State OREGON

CORNER DIAGRAM

T6S R32E

DESCRIBE CORNER MONUMENT FOUND

BLM BRASS CAPPED IRON PIPE-CAP IS MARKED AS IN DIAGRAM.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

BT'S OF RECORD ARE O.K.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
Agency

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

Dennis L. Laylord

PLS 1636

MARCH 1997

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cop. _____

13

USDA-FOREST SERVICE

Index

File No. X-23

T6S

R32E

Merid. Willamette

R.D.

N.F.

CORNER RECORD (SEARCH)

Ref. FSM 7151.4

North Fork John Day

Umatilla

Tract or

Survey No

County

State

Cor.

No.

Umatilla

Oregon

x

1

1

Corner Diagram

1 Describe corner monument found

1

1 Standard BLM brass cap stamped as shown in the corner diagram in a mound of
1 stone.

C-S36

4

1

1968

1

1

1

x

1

x

Photo Identification Data

1 Describe bearing trees or other official accessories found

Photo No.

1 A 21" Ponderosa Pine bears N22.W, 53.8'.

filed at

1 A 11" Ponderosa Pine bears S6 E, 50.8'.

Object Ident.

1

Ident. by

1

Signature

1

x

1

x

Plane Coordinate Position Data

1 Describe corner location relative to near-by features, also how to reach corner

State

Zone

1 From the junction of roads 55 and 5507, follow road 5507 2.4 miles west to a

X

1 cattleguard. Follow a fence 300' east from the cattleguard. From this point,

Y

1 go south 160' to the corner.

Estab. by

1

Agency

1

x

1

x

Signature

Title

Division

Headquarters

Date

7100.52

David L. Hadolok Land Surveyor

Pendleton, OR

July 1988

CORNER RECORD (PERPETUATION)

X _____ X

Monument: Describe new monument set, or work done to preserve existing monument

Set steel guard post 5" west of the monument and attached Forest Service Land Survey Monument sign.

X _____ X

Accessories: Describe new BT's witness objects etc. established, or work done to preserve existing evidence

Made bands around trees and painted bands and scribe blazes red. Attached Forest Service Land Survey Monument and Bearing Tree signs to the trees.

X _____ X

Work done by	David L. Haddock	Title	Land Surveyor	Date	July 1988	State Registration No.	852
Certified cor. record prepared? yes			no x	Filed at		or Agency	
						Date	

X _____ X

REMARKS

X _____ X

Index File No.	X-23	T.6S.	R.32E.	M. Willamette	Tract or Survey No	Cor.
----------------	------	-------	--------	---------------	--------------------	------