

CORNER RECORD (SEARCH)

(Ref. FSM 5151.4)

Tract or
Survey No.

**North Fork
John Dav Unit**


Cor.
No. **AP-506**

T. 6 S. R. 33 E.
Merid. Willamette

R.D. North Fork John Day
N.F. Umatilla

County Umatilla
State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found a 3 1/4" aluminum cap, projecting 1" out of the ground.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

6" Fir Snag, S. 37 1/4 W., 20.8 feet, with burnt out double blaze.
6" Lodgepole Pine Snag, N. 41 W., 46.6 feet, with scribing visible on burnt double blaze.

PHOTO IDENTIFICATION DATA

Photo No.
Filed At.
Object Ident.
Ident. By
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

The corner is located at a point 200 feet southeasterly of the centerline of road 5507 and 200 feet southerly of the centerline of road 52.

PLANE COORDINATE POSITION DATA

State: Zone:
X:
Y:
Datum:

Signature
D. Schlaich

Title
Land Surveyor

Division

Headquarters
S.O.

Date
10/21/1997

FS-7100-52 (3/97)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

RM, 5/8" X 24" rebar with red plastic cap stamped "UMATILLA N.F.", set 20" in the ground, S. 18 1/4 W., 17.2 feet.
8" Lodgepole Pine, N. 31 W., 74.8 feet, scribed "WB/506" "BT" on double blaze.

Work Done By D. Schlaich

Title Land Surveyor

Date 10/21/1997

State Registration No.
or Agency

Certified Corner Record Prepared ?

Yes

No

Filed At:

Date

REMARKS

USDA-FOREST SERVICE

Index

File No.

T. 6 S. R. 33 E.

Merid. WILLAMETTE

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. NFJD

N.F. UMATILLA

Tract or

Survey No. NFJD Unit

County UMATILLA

State OREGON

Cor.

No. AP-506

CORNER DIAGRAM

AP-506



DESCRIBE CORNER MONUMENT FOUND

NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE

PHOTO IDENTIFICATION DATA

Photo No.:

Filed At.:

Object Ident.:

Ident. By:

Signature

DESCRIBE CORNER RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

The corner is located at a point 200 feet southeasterly of the centerline of road 5507 and 200 feet southerly of the centerline of road 52.

PLANE COORDINATE POSITION DATA

State: Oregon Zone: North

X: 2,470,363.99'

Y: 498,962.91'

Datum: NAD1927

Signature

D. Schlaich

Title

Land Surveyor

Division

Headquarters

S.O.

Date

07-1993

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

5/8" by 36" rebar, with a 3 1/4" aluminum cap, flush with the ground, marked "NFJD WILDERNESS AP-506 RLS 2308 1993".

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

5" Lodgepole Pine, N. 40° W., 46.6 ft., mkd. "WB/506""BT" on double blaze.

6" Fir, S. 39° W., 20.8 ft., mkd. "WB/506"BT" on double blaze.

Both BT's have a 3/4" brass washer stamped "RLS 2308" nailed next to "BT" scribing on lower blaze.

Work Done By **D. Schlaich**

Title Land Surveyor

Date 07-1993

State Registration No.
or Agency

Certified Cor. Record Prepared ? **NO**

Filed At:

Date

REMARKS

Index File No.

T.

6 S.

R.

33 E.

M.

W.M.

Tract or Survey No.

NFJD Unit

Cor.

AP-506