Chains	
40.00	The cor. point falls on ledge, 4x3x3 ft. above ground. I mark with a cross at the exact cor. point, for $\frac{1}{4}$ Sec. cor., with $\frac{1}{4}$ on N. side of cross, from which
	A fir, 12 ins. diam., bears S. 53° W., 43 lks. dist., marked $\frac{1}{4}$ S 29 B T.
	A fir, 24 ins. diam., bears N. 20° W., 37 lks. dist., marked $\frac{1}{4}$ S 20 B T.
	This cor. stands about 400 ft. above the Sec. cor.
55.00	Enter scattering timber, bears N. and S.
58.75	Leave undergrowth, bears N. and S.
63.00	Top of ridge, bears N. and S. Descend gradually
80.24	The cor. of Secs. 19, 20, 29 and 30.
	Land, mountainous.
	Soil, stony and loam; 3rd and 2nd rate.
	Timber, fir, pine, spruce and tamarack.
	Undergrowth, small firs, mountain laurel and huckleberry.
	Mountainous land, 80.24 chs.
	W. on random line bet. Secs. 19 and 30.
40.00	Set temp. $\frac{1}{2}$ Sec. cor.
100.65	Intersect W. bdy. of Tp. 352 lks. S. of the cor. of Secs. 19, 24, 25 and 30, which is a basalt stone, 20x12x10 ins. loosely set in mound of stone.
	The bearing trees as described by the surveyor general have been destroyed. I restablish the cor. at the same place as follows.
	Set basalt stone, 20x12x10 ins., 15 ins. the ground for cor. of Secs. 24 and 25, marked with 4 notches on N. and 2 notches on S. edges, from which
	A fir, 10 ins. diam., bears S. 15° W. 34 lks. dist., marked T 2 N R 38 E., S 25 B T.
	A fir, 12 ins. diam., bears N. 30$\frac{1}{2}$° W. 51 lks. dist., marked T 2 N R 38 E., S 24 B T.
	At point of intersection set ironstone, 20x10x8 ins., 15 ins. in the ground for closing cor. of Secs. 19 and 30, marked C C on E. face; with 4 grooves on N. and