Subdivisional Lines of T. 4 S., R. 30 E. W.M.

Chains		Feet
	A Pine 16 ins. diam. brs. S. 40° E. 72 lks. dist.	
	marked & S. B.T.	
	No other trees, raised mound of stone alongside Cor.	(
80.28	The Cor. to Secs. 14, 15, 22 and 23.	1
	Land; surface udnulating,	
- "	Soil; 3rd and 2nd rate; Pine, Tamarack and Fir.	Y
	Timber thick in places with some underbrush, but mostly	
	open and scattering.	
	10 294 10 10 2 2 2	
	N. bet. Sec. 14 & 15.	
	Var. 20° 45' E.	
40.00	Set a basalt stone 12 x 10 x 8 ins., 8 ins. in ground	
	on N. slope for & Sec. Cor., marked & on W. face.	
37.	A Pine 16 ins. diam. brs. N. 88° E. 74 lks. dist.	
	marked & S.B.T.	
	A Pine 40 ins. diam. brs. S. 10° W. 73 lks. dist.	/
at 2	marked & S. B.T.	1
74.25	A spring branch, course N.W.	
	Descent about 200 ft., and leave timber, course N.W. &	
-290	S.E.	
80.00	Set a post 4 ft. long 4 ins. square in mound of stone on	
00,00	S.W. slope for Cor. to Secs. 10, 11, 14 and 15, marked,	
	2. 44., 3. 44 oT. 4 S., S. 11 on N.E.	
	R. 30 E., S. 14 on S.E.,	
	S. 15 on S.W. and S. 10 on N.W., also	
	with 4 notches on S. and 2 notches on E. edges.	
	20 S 15 85 31	
	Land; surface broken,	1
	Soil; 2nd and 3rd rate, heavily timbered with Pine, Tamarack and Fir.	
	Maria de Caración	
	Timber, except N. 6 chs., a few glades.	
	D. As a pandam 21 has been Care 22 and 21	
	E. on a random line bet. Sec. 11 and 14.	
70	Var. 19° 00' E.	10
	Ascending S.W. slope,	
40.00	Set temp. & Sec. Cor.	